



# Mostly Printed CNC – Assembly Instructions

## Index

0 – Calculate the length of your conduits, belts, etc.....	2
Conduits.....	2
Belts.....	2
All-thread.....	2
1 – Parts you need.....	2
Unit-independent.....	3
Imperial.....	3
Metric.....	3
2 – Part preparation.....	4
4x Roller_F + Roller_Motor_Mount.....	4
2x Middle_Joiner.....	4
2x Middle_End.....	5
4x Middle_Z.....	5
4x Corner_Block + Corner_Block_Lock.....	5
1x Z_Motor_Mount.....	5
4x NEMA Stepper Motor + GT2 16tooth Belt Pulley.....	5
3 – Middle Part Assembly.....	6
Step 1 – Joining the Middle_Joiners and Z_Nut_Lock.....	6
Step 2 – Adding Middle_Z and Middle_End.....	7
4 – Frame Assembly.....	8
5 – Adding the belts.....	10
6 – Putting the Z tower together.....	12
Prepare your conduits.....	12
Prepare the tool_holder_nut_traps.....	13
The conduits-tool_holder-tool_holder_nut_traps marriage.....	13
7 – You’re finished with the plastic and metal part.....	15



# Mostly Printed CNC – Assembly Instructions

0 – Calculate the length of your conduits, belts, etc.

## Conduits

The length of the conduits depends on your desired workroom. Here is what you need to add to compensate the loss of length caused by mounts etc.

On the X and Y axis you have to add 11" (27cm) and on the Z axis 7.9" (20cm).

Example: You want your CNC be able to move 30" on the X axis, 25" on the Y axis and 10" on the Z axis, you need:

three 41" conduits for X,  
three 36" conduits for Y and  
two 17.9" conduits for Z

## Belts

Use your calculated length for X and Y axis and add another 2". Using the example from above you would need:

2x 43" belt  
2x 38" belt

(Z axis doesn't need a belt, it has an all-thread)

## All-thread

Subtract 2" from the length of your Z conduit, this is the length for your all-thread.

## 1 – Parts you need





# Mostly Printed CNC – Assembly Instructions

## Unit-independent

- 53x 608zz (better: 608rs) bearings
- 5x NEMA 17 stepper motor
- 4x GT2 16tooth belt pulley
- GT2 belt (length: look at “0 – Calculate the length of your conduits, belts, etc.”)
- at least 20 zip ties
- 20x M3x10 screws for NEMA Stepper Motors

## Imperial

- 1x  $\frac{5}{16}$  all-thread (length: look at “0 – Calculate the length of your conduits, belts, etc.”)
- 28x bolt  $\frac{5}{16}$  x 1.25
- 2x bolt  $\frac{5}{16}$  x 1.5
- 2x bolt  $\frac{5}{16}$  x 1.75
- 8x bolt  $\frac{5}{16}$  x 2.5
- 4x bolt  $\frac{5}{16}$  x 3
- 8x  $\frac{5}{16}$  fender washer
- 16x  $\frac{5}{16}$  speed washer
- 3x  $\frac{5}{16}$  nut
- 44x  $\frac{5}{16}$  lock nut
- 1x  $\frac{5}{16}$  x 0.75 coupler nut
- 2x screw  $\frac{6}{32}$  x 0.5
- 34x screw  $\frac{6}{32}$  x 0.75
- 36x  $\frac{6}{32}$  lock nut

## Metric

The description of the bolts mean: e.g. M8x30 = bolt with 8mm diameter, 30mm length (without the head), regular pitch, they are called “Maschinenschrauben”.

- 2x M4x10
- 2x M4x16
- 28x M4x20
- 4x M4x20 (with small heads as they have to fit within the tool holders)
- 36x M4 nut
- 1x M8 coupler nut
- 1x M8 all-thread (length: look at “0 – Calculate the length of your conduits, belts, etc.”)
- 28x M8x30
- 4x M8x40
- 8x M8x70
- 4x M8x80
- 3x M8 nut
- 44x M8 lock nut (these won't move without force as soon as they are on a bolt)
- 16x M8 washer (8mm inner, 15,7mm outer diameter) „M8 Beilagscheiben“
- 8x M8 washer (8mm inner, 26,8mm outer diameter) „M8 Bauscheiben“



# Mostly Printed CNC – Assembly Instructions

## 2 – Part preparation



All bolts with bearings on it must not be tightened too strong. It's perfect when the bolts are turnable by hand with a bit force after you tightened the lock nuts on them.



All parts that are there more than once are all prepared the same way. The named number of bolts etc. is for each part, so if there's a 4x in front of the part-headline that means, you need to prepare four of this parts and each parts needs the given number of bolts etc.

### 4x Roller\_F + Roller\_Motor\_Mount

- 2x bolt  $\frac{5}{16} \times 2.5$  (M8x70)
- 2x  $\frac{5}{16}$  fender washer (big M8 washer)
- 4x  $\frac{5}{16}$  speed washer (small M8 washer)
- 7x 608zz bearing
- 3x bolt  $\frac{5}{16} \times 1.25$  (M8x30)
- 5x  $\frac{5}{16}$  lock nut (M8 lock nut)

Put one bearing on each of the short bolts, insert them as shown above and put the locking nuts on them.

The order for the longer bolts is: bolt – fender washer – speed washer – 608zz – speed washer – Roller\_Motor\_Mount – Roller\_F – 608zz – lock nut.

### 2x Middle\_Joiner

- 2x 608zz bearing



## Mostly Printed CNC – Assembly Instructions

- 2x bolt  $\frac{5}{16}$  x 1.25
- 2x  $\frac{5}{16}$  lock nut

### 2x Middle\_End

- 3x 608zz bearing
- 2x bolt  $\frac{5}{16}$  x 1.25 (M8x30)
- 2x bolt  $\frac{5}{16}$  x 1.5 (M8x40)
- 3x  $\frac{5}{16}$  lock nut (M8 lock nut)

### 4x Middle\_Z

- 2x 608zz bearing
- 2x bolt  $\frac{5}{16}$  x 1.25 (M8x30)
- 2x  $\frac{5}{16}$  lock nut (M8 lock nut)


### 4x Corner\_Block + Corner\_Block\_Lock

- 4x screw  $\frac{6}{32}$  x 0.75 (M4x20)
- 4x  $\frac{6}{32}$  lock nut (M4 lock nut)

### 1x Z\_Motor\_Mount

- 2x screw  $\frac{6}{32}$  x 0.75 (M4x16)
- 2x  $\frac{6}{32}$  lock nut (M4 lock nut)

### 4x NEMA Stepper Motor + GT2 16tooth Belt Pulley



Leave a little gap between the stepper motor and the pulley, so the pulley can turn free without striking against the stepper.



If you have trouble with your belts later being pressed against the outer fender washers, just turn your pulley around and the teeth are closer to the stepper motor.



## Mostly Printed CNC – Assembly Instructions

### 3 – Middle Part Assembly

#### Step 1 – Joining the Middle\_Joiners and Z\_Nut\_Lock



- 2x bolt  $\frac{5}{16} \times 1.5$  (M8x40)
- 2x  $\frac{5}{16}$  lock nut (M8 lock nut)
- 1x  $\frac{5}{16}$  coupler nut (M8 coupler nut)
- 2x 608zz bearing
- 2x screw  $\frac{6}{32} \times 0.75$  (M4x20)
- 2x  $\frac{6}{32}$  lock nut (M4 lock nut)

Begin with the two Middle\_Joiner and let the locking nuts very loose. Insert the coupler nut into the Z\_Nut\_Lock and attach it to the two joiners and tighten the nuts for the Z\_Nut\_Lock. Now tighten the nuts of the two bolts.



## Mostly Printed CNC – Assembly Instructions

Step 2 – Adding Middle\_Z and Middle\_End




- 4x bolt  $\frac{5}{16} \times 3$  (M8x80)
- 4x  $\frac{5}{16}$  lock nut (M8 lock nut)
- 4x 608zz bearing




## Mostly Printed CNC – Assembly Instructions

### 4 – Frame Assembly



Put one finished Roller\_F on each conduit, but don't tighten any screws of the Corner\_Blocks yet. Insert the two remaining conduits into the assembled middle part (the Z\_Nut\_Lock should be looking towards Corner\_Block 1). Now put the middle part with the conduits on the Roller\_Fs and put the Roller\_Locks on the Roller\_Fs. You'll need 2x screw  $\frac{6}{32} \times 0.75$  (M4x20) and 2x  $\frac{6}{32}$  lock nut (M4 lock nut) for each Roller\_Lock (don't tighten yet ;-)








## Mostly Printed CNC – Assembly Instructions

The upper X and Y conduits should be flush mount with the corner blocks 3 and 4. Tighten all screws of corner block 3 and 4. Now move the middle part to the right upper corner and tighten all screws of the Roller\_Locks of the Y Rollers (left and right one) and of the upper X Roller\_F.




Move the middle part to the lower left corner. Move the conduits of Corner\_Block 1 and 2 if they are too close / too wide. As soon as you can move the middle part without being blocked in any direction move it back to the lower left corner. Now tighten all screws of the remaining lower X Roller\_F and of Corner\_Block 1 and 2.




## Mostly Printed CNC – Assembly Instructions

### 5 – Adding the belts





## Mostly Printed CNC – Assembly Instructions



Lock each belt on one end. Use the holes in the corner\_blocks for the belts on the Y axis and the holes in the corner\_block\_locks for the belts on the X axis. Start with the X axis and mount the belt as shown above.




Now lock the belt to the other end, the belts don't really need to be highly tightened. Better you leave some room to tighten them a bit more if needed. As soon as the Roller\_Motor\_Mount is leaning forwards the belt is tightened too heavily.

When you finished the two belts on the X axis do the same with the Y axis.



## Mostly Printed CNC – Assembly Instructions

### 6 – Putting the Z tower together



You can build the Z tower separately and when finished you can add it to the middle part. On this picture you can see the addon “Z Adjust Knob”, which is very useful.

#### Prepare your conduits



Lay the tool\_holder\_nut\_trap on one of your z-conduits. Put a pencil through the holes and mark the points where you need to drill. Repeat with the other conduit and drill the holes.



## Mostly Printed CNC – Assembly Instructions

Prepare the `tool_holder_nut_traps`




Put a nut in each placeholder and use a bit tape to avoid that they can fall out again.



Now insert the `nut_traps` in your conduits, move them until you see that both holes in your conduits match the holes in the `nut_trap`.

The `conduits-tool_holder-tool_holder_nut_traps` marriage




Put a screw in the `tool_holder` and now with a bit patience you can tighten the screw through `tool_holder` – `conduit` – `nut_trap` and with the nut.

It's easier to start with the one at the bottom because you can hold the `nut_trap` with your finger.



## Mostly Printed CNC – Assembly Instructions



Repeat with the second tool\_holder and then add the second conduit.

Well done!

Add the Z\_Motor\_Mount to the upper end of your conduits (the bulge has to point to the same direction as your tool\_holders do) and tighten the screws. If you want to use the Z\_Adjust\_Knob add it now or never. Move the all-thread from below through the Z\_Motor\_Mount and add the Rigid\_Coupler. Put the last stepper motor on the Z\_Motor\_Mount and use four M3x10 screws to mount it. Now tighten the screws of the Rigid\_Coupler.

To insert the Z tower put it on the middle part (tool holder pointing to the lower left corner) and insert it between the Middle\_Zs. As soon as the all-thread touches the coupler-nut in the middle part you can use the Z\_Adjust\_Knob and screw the Z tower a bit down (until the all-thread comes out of the coupler\_nut at the other end).



## Mostly Printed CNC – Assembly Instructions

### 7 – You're finished with the plastic and metal part

Congrats! Your frame is ready for some cables and electronics.

Please feel free to ask any question here:

<http://www.vicious1.com/forums/topic/assembly-instructions/>

Some links:

Mostly Printed CNC on thingiverse.com: <http://www.thingiverse.com/thing:724999>

Mostly Printed CNC (International Edition): <http://www.thingiverse.com/thing:790533>

Preview